

Fig.	Description of part	NO.
1.	Self tapping screw $\Phi 4 \times 20$	4
2.	Gear box	1
3.	Motor gear	1
4.	Electric machinery	1
5.	inductance	2
6.	Casing cover	1
7.	Self tapping screw $\Phi 3 \times 16$	1
8.	Self tapping screw $\Phi 3 \times 16$	9
9.	LCD777-1S Push rod	1
10.	switch	1
11.	Self tapping screw $\Phi 3 \times 10$	1
12.	Bracket	1
13.	Battery pack	2
14.	LED light	1
15.	D770-3 Transparent lamp shade	1
16.	Strong magnetic	2
17.	Chassis bottom	1

